


ART NR. 50423-000-71, 50423-000-53

Three-wires Mini Stragight Connector



Three wires track

Make the side with two copper cores on the same side as the protruding part of the ground wire

Loosen the two screws B on the three-wire mini connector first, then insert the three-wire tracks into the connector in the direction of the arrow, and finally tighten the screws B